

Important Notice

Upon initial inspection, some new shocks may have a small amount of oil in the area of the seal. This is a normal occurrence following the manufacturing process and **does not** indicate a problem with the shock.

D3162